

Date: Thursday, 15/03/2007 1:15:00 PM  
 User: Linda Lacelle

## Process Sheet

<b>Customer</b> : CU-DAR001 Dart Helicopters Services	<b>Drawing Name</b> : 407 STEP ASSEMBLY
<b>Job Number</b> : 31241	
<b>Estimate Number</b> : 11795	
<b>P.O. Number</b> : N/A	<b>Part Number</b> : D206628033
<b>This Issue</b> : 15/03/2007 <b>S.O. No.</b> : N/A	<b>Drawing Number</b> : N/A
<b>Prsht Rev.</b> : NC	<b>Project Number</b> : N/A
<b>First Issue</b> : N/A <b>Type</b> : LARGE FAB ASSY	<b>Drawing Revision</b> : N/A
<b>Previous Run</b> : 30806	<b>Material</b> : N/A
<b>Written By</b> : _____	<b>Due Date</b> : 30/03/2007 <b>Qty:</b> 2 <b>Um:</b> Each
<b>Checked &amp; Approved By</b> : _____	
<b>Comment</b> : Est Rev:D As Per Ecn 766 06-01-06 JLM	

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	DC	DOCUMENT CONTROL
-----	----	------------------

**Comment:** DOCUMENT CONTROL

Photocopy blue file and type labels as per RPP D206-628-033 CHG.002

CZ

RS 070315

2.0	31241A	FLOAT STEP ASSEMBLY LH (206/407)
-----	--------	----------------------------------

**Comment:** Sub-Component SUB-ASSEMBLY

206B STEP ASSY, LH

D2842-041 B 31241A

3.0	PACKAGING 1	PACKAGING RESOURCE #1
-----	-------------	-----------------------

**Comment:** PACKAGING RESOURCE #1

Pick Packing Kit

4.0	D27313	Mounting Lug
-----	--------	--------------

**Comment:** Qty.: 4.0000 Each(s)/Unit Total: 8.0000 Each(s)

Pick:

Qty	Part Number	Description	Batch
4	D2731-3	Mounting Lug	B27420

B27420

B27740

5.0	D28441	Arm
-----	--------	-----

**Comment:** Qty.: 2.0000 Each(s)/Unit Total: 4.0000 Each(s)

Pick: Packing Kit

Qty	Part Number	Description	Batch
			B26788
			B14086

B26788

B14086

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Date: Thursday, 15/03/2007 1:15:00 PM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 407 STEP ASSEMBLY

Job Number: 31241

Part Number: D206628033

Job Number:



Seq. #:

Machine Or Operation:

Description :

2 D2844-1

Arm

6.0

D28443

Arm



Comment: Qty.: 1.0000 Each(s)/Unit Total : 2.0000 Each(s)

Pick: Packing Kit

Qty Part Number

Description Batch

1 D2844-3

Arm

B11187 ✓

7.0

D2856400

Abrasion Strip



Comment: Qty.: 1.2605 f(s)/Unit Total : 2.5211 f(s)

Pick :

Qty Part #

Description

Batch

2 D2856-400 6.25" Abrasion Strip

B30822 ✓

8.0

D3394041

LUG ASS'Y



Comment: Qty.: 4.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

4 D3394-041 LUG ASS,Y

B329794 ✓

9.0

AN3C4A

BOLT



Comment: Qty.: 3.0000 Each(s)/Unit Total : 6.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

3 AN3C4A

Bolt

M103641 ✓

10.0

AN4C12A

BOLT



Comment: Qty.: 8.0000 Each(s)/Unit Total : 16.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

8 AN4C12A

Bolt

M103691 ✓

7/5/16 SQ

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 15/03/2007 1:15:00 PM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 407 STEP ASSEMBLY

Job Number: 31241

Part Number: D206628033

Job Number:



Seq. #:

Machine Or Operation:

Description :

11.0

AN4C15A

Bolt



Comment: Qty.: 4.0000 Each(s)/Unit Total : 8.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

4 AN4C15A

Bolt

~~M101291~~ X

12.0

AN960C10

WASHER



Comment: Qty.: 3.0000 EACH(s)/Unit Total : 6.0000 EACH(s)

Pick:

Qty Part Number

Description

Batch

3 AN960C10

WASHER

~~M101064~~ ✓

13.0

AN960JD416L

Washer



Comment: Qty.: 24.0000 Each(s)/Unit Total : 48.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

24 AN960JD416L

Washer

~~M103691~~ ✓

M103691

PTO

14.0

NAS1515H4L

Inventory



Comment: Qty.: 24.0000 Each(s)/Unit Total : 48.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

24 NAS1515H4L

Washer

~~M101542~~ ✓

M101542

15.0

MS210434

Nut



Comment: Qty.: 12.0000 Each(s)/Unit Total : 24.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

12 MS21043-4

Nut (or MS21042-4)

~~M102959~~ ✓

16.0

NAS1515H3

Washer



Comment: Qty.: 3.0000 Each(s)/Unit Total : 6.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

3 NAS1515H3

Washer

~~M100993~~ ✓

7/5/16 SO

**Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
15.07.17	13	Permanent change	U	07.05.17		U	

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

**NOTE:** Date & initial all entries

Date: Thursday, 15/03/2007 1:15:00 PM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 407 STEP ASSEMBLY

Job Number: 31241

Part Number: D206628033

Job Number:



Seq. #:

Machine Or Operation:

Description :

17.0

QC4

INSPECT 100% KITS FOR COMPLETENESS



Comment: INSPECT 100% KITS FOR COMPLETENESS

*EP 02/05/17 (2)*

*C207/05/17 (2)*

18.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and pack for shipping as per PPP D206-628-033

Location: \_\_\_\_\_

PPP Rev: \_\_\_\_\_

*Rev D*

*7/05/17*

*EP 02/05/17 (2)*  
*SP*

19.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

*(2)*  
*207/05/02*

Job Completion



*C207/05/22*

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries



D206-628-013-023-024/-033/-033  
ACCESS-STEPS

## PARTS LIST

IIN-D206-628  
Page 12 of 12

Qty -013	Qty -014	Qty -023	Qty -024
X	X		
		X	
			X
2	2		
2	2	4	4
1	1		
		1	
		2	1
2	2	1	2
1	1		1
1	1		1
2	2	2	2
2	2		
4	4		
2	2	4	4
2	2	4	4
4	4	8	8
2	2	3	3
4	4	4	4
4	4	4	4
2	2	3	3
24	24	24	24
24	24	24	24
12	12	12	12
2	2	3	3

\*DE

Qty -033	Qty -034	Part Number	Description
		D206-628-013	206 A/B FLOAT STEP INST. LH
		D206-628-014	206 A/B FLOAT STEP INST. RH
		D206-628-023	206 L/L1/L3/L4 FLOAT STEP INST. LH
X		D206-628-024	206 L/L1/L3/L4 FLOAT STEP INST. RH
	X	D206-628-033	407 FLOAT STEP INST. LH
		D206-628-034	407 FLOAT STEP INST. RH
4	4	D2731-3	MOUNTING LUG
		D2731-7	MOUNTING LUG
		D2841-041	FLOAT STEP ASSEMBLY LH
1		D2841-042	FLOAT STEP ASSEMBLY RH
	1	D2842-041	FLOAT STEP ASSEMBLY LH
2	2	D2842-042	FLOAT STEP ASSEMBLY RH
1	1	D2844-1	FLOAT STEP ASSEMBLY LH
		D2844-3	FLOAT STEP ASSEMBLY RH
2	2	D2845	ARM
		D2856-400-625	ARM
4	4	D2856-400-690	ARM
4	4	D3394-041	ABRASION STRIP
8	8	*D3394-1	ABRASION STRIP
		*MS35489-93	MOUNTING LUG
		D3394-043	*MOUNTING LUG
		*D3394-3	*GROMMET
		*MS35489-93	MOUNTING LUG
3	3		*MOUNTING LUG
		AN3C4A	*GROMMET
8	8	AN4C11A	BOLT
		AN4C12A	BOLT
4	4	AN4C13A	BOLT
3	3	AN4C15A	BOLT
24	24	AN960C10	BOLT
24	24	AN960C416L	WASHER
12	12	NAS1515H4L	WASHER
3	3	MS21043-4	WASHER
		NAS1515H3	NUT
			WASHER

AT PART IS INCLUDED IN ASSEMBLY ABOVE

REFERENCE ONLY

DOCUMENT IS PRIVATE AND  
OR COMMUCONFIDENTIAL  
ICATED TO

NYC

COPYRIGHT © 2005 BY DART AEROSPACE USA, INC.



IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE  
OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision: E

Date: 05.09.20

Date: Thursday, 15/03/2007 1:15:29 PM  
 User: Linda Lacelle

## Process Sheet

<b>Customer</b>	: CU-DAR001 Dart Helicopters Services	<b>Drawing Name</b>	: FLOAT STEP ASSEMBLY LH (206/407)
<b>Job Number</b>	: 31241A		
<b>Estimate Number</b>	: 11664		
<b>P.O. Number</b>	: <i>N/A</i>	<b>Part Number</b>	: D2842041
<b>This Issue</b>	: 15/03/2007	<b>Drawing Number</b>	: D2842 REV B
<b>Prsht Rev.</b>	: NC	<b>Project Number</b>	: N/A
<b>First Issue</b>	: <i>N/A</i>	<b>Drawing Revision</b>	: B
<b>Previous Run</b>	: 30806A	<b>Material</b>	: <i>N/A</i>
	<b>Type</b> : LARGE FAB ASSY	<b>Due Date</b>	: 30/03/2007
<b>Written By</b>	: 	<b>Qty:</b>	2 Um: Each
<b>Checked &amp; Approved By</b>	: 		
<b>Comment</b>	: Est Rev:D As Per Ecn 766 06-01-06 JLM		

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

1.0	D2622120C	Extrusion
-----	-----------	-----------



**Comment:** Qty.: 1.0000 Each(s)/Unit Total : 2.0000 Each(s)

Qty	Part #	Description	Batch:
1	D2622-120C	Extrusion	<i>B29607</i>

Check Material for any Dents or Defects

*P.E. 07.04.17* 2

2.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1
-----	-------------	------------------------------



**Comment:** LARGE FABRICATION RESOURCE 1

1-Cut D2842-1 using D2622 extrusion as per Dwg D2842

2-Drill D2842-1 using Jig DT8271 as per Dwg D2842

3-Deburr and bevel ends for welding

*P.E. 07.04.17* 2

*P.E. 07.04.17* 2

*P.E. 07.04.17* 2

3.0	D2734	206 Step Endplate
-----	-------	-------------------



**Comment:** Qty.: 2.0000 Each(s)/Unit Total : 4.0000 Each(s)

206 Step Endplate

Pick:

Qty	Part Number	Description	Batch
2	D2734	End Cap	<i>B29340</i>

*P.E. 07.04.17* 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: \_\_\_\_\_ PAR #: \_\_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_\_ Date: \_\_\_\_\_

QA: N/C Closed: \_\_\_\_\_ Date: \_\_\_\_\_

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Date: Thursday, 15/03/2007 1:15:29 PM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT STEP ASSEMBLY LH (206/407)

Job Number: 31241A

Part Number: D2842041

Job Number:



Seq. #:

Machine Or Operation:

Description :

4.0

D34593

plate



Comment: Qty.: 2.0000 Each(s)/Unit Total: 4.0000 Each(s)

Pick:

Qty Part Number Description Batch

2 D3459-3 Lug

*50648=2*  
*B31238=2*

*LE. 07.04.17 2*

5.0

D34591

plate



Comment: Qty.: 2.0000 Each(s)/Unit Total: 4.0000 Each(s)

Pick:

Qty Part Number Description

2 D3459-1 Lug

Batch

*B30909*

*LE. 07.04.17 2*

6.0

LARGE FAB 1

LARGE FABRICATION RESOURCE 1



Comment: LARGE FABRICATION RESOURCE 1

1-Weld one end cap and (2) lugs using Jig DT

followed by DT as per Dwg D2842

A/R

AL Rod

Batch:

*M100237*  
*M103317*

2-Grind end cap weld flush

*LE. 07.04.17 2*

*LE. 07.04.17 2*

7.0

QC5/9

WELD INSPECTION



Comment: WELD INSPECTION

8.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

Chemical Conversion Coat as per QSI 005 4.1

*M.R. 07/05/07*

Date: Thursday, 15/03/2007 1:15:29 PM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT STEP ASSEMBLY LH (206/407)

Job Number: 31241A

Part Number: D2842041

Job Number:



Seq. #:	Machine Or Operation:	Description :
---------	-----------------------	---------------

9.0	QC3	INSPECT POWDER COAT/CHEMICAL CONVERSION
-----	-----	---



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

FF 07-05-08 2

10.0	LARGE FAB 1	LARGE FABRICATION RESOURCE 1
------	-------------	------------------------------



Comment: LARGE FABRICATION RESOURCE 1

1-Remove alodine prior to welding.

Weld end cap as per Dwg D2842.

A/R AL Rod Batch: M102956

FF 07.05.08 2  
FF 07.05.09 2

2-Grind end cap weld flush.

11.0	QC9	VISUAL WELDING INSPECTION
------	-----	---------------------------



Comment: VISUAL WELDING INSPECTION

11/07/05/10 (2)

12.0	QC5	INSPECT WORK TO CURRENT STEP
------	-----	------------------------------



Comment: INSPECT WORK TO CURRENT STEP

11/07/05/10 (2)

13.0	POWDER COATING	POWDER COATING
------	----------------	----------------



Comment: POWDER COATING

Touch up Alodine end cap and Powder Coat Gloss White (Ref: 4.3.5.1) as per QSI 005 4.3

touch up alodine FR 07/05/15 (2)

11/07-05-15 (2)

14.0	NAS1329C3KB130	insert
------	----------------	--------



Comment: Qty.: 3.0000 Each(s)/Unit Total: 6.0000 Each(s)

Insert

Pick:

Qty Part Number

Description Batch

3 NAS1329C3KB130Insert

M102974

15.0	MS27039C107	screw
------	-------------	-------



Comment: Qty.: 3.0000 Each(s)/Unit Total: 6.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

3 MS27039C1-07

Screw

M19522

FR 07/05/16 (2)

Date: Thursday, 15/03/2007 1:15:30 PM  
User: Linda Lacelle

## Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: FLOAT STEP ASSEMBLY LH (206/407)

Job Number: 31241A

Part Number: D2842041

Job Number:



Seq. #:

Machine Or Operation:

Description:

16.0

NAS1515H3L

WASHER



Comment: Qty.: 3.0000 Each(s)/Unit Total: 6.0000 Each(s)

Pick:

Qty Part Number

Description Batch

3

NAS1515H3L

WASHER

*m103641*

17.0

AN960C10L

washer



Comment: Qty.: 3.0000 Each(s)/Unit Total: 6.0000 Each(s)

Pick:

Qty Part Number

Description

Batch

3

AN960C10L

WASHER

*m104215*

18.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: LARGE FABRICATION RESOURCE 1

1-Install inserts as per Dwg D2842

2-Wing Walk as per Dwg D2842 and QSI 005 4.1

Batch: *m103707*

*Feb 02/05/16 (2)*

19.0

QC3/5

INSPECT WORK/WING WALK



Comment: INSPECT WORK/WING WALK

*02/05/17 (2)*

20.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location: \_\_\_\_\_

*02/05/17 (2) 00P3/241 7/5/17 S9*

21.0

QC21

FINAL INSPECTION/W/O RELEASE




Comment: FINAL INSPECTION/W/O RELEASE

Job Completion



*02/05/18*

**DART**




NAS1329C3KB130 (OR AESS10KB130) INSERTS  
MS27039C1-07 SCREW  
NAS1515H3L WASHER  
AN960C10L WASHER  
(TYP 3 PLACES)

D2842-041 LH STEP ASSEMBLY (SHOWN)  
D2842-042 RH STEP ASSEMBLY (OPPOSITE)

**D2842-041/-042 FLOAT STEP ASSEMBLY PARTS LIST**

QTY -041	QTY -042	PART NUMBER	DESCRIPTION
X		D2842-041	LH STEP ASSEMBLY
	X	D2842-042	RH STEP ASSEMBLY
1	1	D2622-118	EXTRUSION
2	2	D2734	END PLATE
2	2	D3459-1	PLATE
2	2	D3459-3	PLATE
3	3	NAS1329C3KB130 (OR AESS10KB130)	INSERT
3	3	MS27039C1-07	SCREW
3	3	NAS1515H3L	WASHER
3	3	AN960C10L	WASHER

NO. 312414  
WORK ORDER  
UNCONTROLLED COPY  
SUBJECT TO AMENDMENT  
WITHOUT NOTICE  
SHOP COPY  
RETURN TO  
ENGINEERING



**D2842-041/-042 FLOAT STEP ASSEMBLY**

- 1) MAKE FROM EXTRUSION D2622
- 2) WELD PER DART QSI 004.
- 3) FINISH: CHEMICAL CONVERSION COAT PER DART QSI 005 4.1  
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3  
APPLY BLACK ANTI-SKID PAINT PER DART QSI 005 4.4
- 4) ALL DIMENSIONS ARE IN INCHES
- 5) ALL TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED

RELEASED  
05-11-14



DESIGN	KE	DRAWN BY	PH	<b>DART AEROSPACE USA, INC.</b>
CHECKED	<i>[Signature]</i>	APPROVED	<i>[Signature]</i>	PORT HADLOCK, WA
DATE	05.09.23	DRAWING NO.	D2842	REV. B
		TITLE	206L/407 FLOAT STEP ASSEMBLY	SHEET 1 OF 1
			NEW ISSUE	SCALE
			RE-DESIGN, ADD D3459-1/-3	

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Copyright © 2005 by DART AEROSPACE USA, INC.

Date: Friday, 07/09/2007 1:11:06 PM  
User: Linda Lacelle

# Process Sheet

Customer : CC-DAR01 Dart Aerospace Ltd.	Drawing Name : D206-628
Job Number : 34468	
Estimate Number : 10804	
P.O. Number : N/A	Part Number : Z_CUSTOM
This Issue : 07/09/2007 S.O. No. : N/A	Drawing Number : ECN 1029
Prsht Rev. : NC	Project Number : N/A
First Issue : N/A Type : LARGE FAB ASSY	Drawing Revision : N/A
Previous Run : 00015	Material : N/A
Written By : 	Due Date : 14/09/2007 Qty: 1 Um: Each
Checked & Approved By : 	
Comment :	

Additional Product

Job Number:



Seq. #: Machine Or Operation:

Description :

1.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

PULL FROM STK - ADD NEW PAPERWORK PER ECN 1029

EASA STC: EASA.IM.R.S.01339:

D206-628-011

33411 (3X) 33038 (4X) 32979 (1X)

D206-628-012

32980 (1X) 33892 (1X)

D206-628-013

D206-628-014

18533 (1X) 18943 (1X)

D206-628-021

31976 (3X) 33756 (3X) 29739 (1X)

D206-628-021BL

33649 (2X)

D206-628-022

33757 - 31977 (3X)

D206-628-023

33921 (1X)

D206-628-024

33922 (1X)

D206-628-031

31010 (4X)

D206-628-032

29738 (1X) 31011 (4X)

D206-628-033

30806 (2X) 31241 (2X)

D206-628-034

30807 (2X)

7/8/11 SP